CERTIFICATE OF STRUCTURAL SOUNDNESS

Certified that the existing Three storied RCC Building (G.F+2 floors) situated in 7-122/1, Kurnool Road, Ongole Municipal Corporation, Ongole which is going to use by St.Xavier's High School Dise Code: (28184490802) is in Good Condition and found that both Physically and Structurally Sound Enough at the time of inspection and fit to run the school.

(Roc.No.1828/E2/2023)

Executive Engineer
Ongole Municipal Corporation

